DEPARTMENT OF TRANSPORTATION

REPORT OF BRIDGE SURVEY

U.S. COAST GUARD CG-2541-D11 (Rev2/99)

INSTRUCTIONS: 1. Submit this report to the Auxiliary Coordinator as soon as possible after conducting the survey.

- 2. The best time to survey bridges is shortly before sunset so you can observe any hazards or discrepancies before dark, then observe the lights after dark.
- 3. If conducting the survey by land, respect all property rights. DO NOT TRESPASS.
- 4. Auxiliarists do not have law enforcement authority. Take care that your survey is not interpreted as a law enforcement action.
- 5. Minor discrepancies (e.g. one light out, clearance gauges hard to read) should be reported by mail. More serious problems (e.g. most or all lights out, hazards to navigation, bridge malfunction) should be reported to the nearest Coast Guard Group Office by telephone or radiotelephone. If in doubt, report it.

reported to the nearest Coast Guard Group Office by telephone or radiotelephone. If in doubt, report it.							
NAME OF BRIDGE				L	ATITUDE	LONGITUDE	
FRUITVALE RY BRIDGE					37 46.2' N	122 13.8' W	
NAME OF WATERWAY				N	IILES ABOVE MOUTH	TYPE OF BRIDGE	
OAKLAND INNER HARBOR				5	5.6	VL	
NAME/ADRESS OF BRIDGE OWNER				NAME/ADDRESS OF BRIDGE OPERATOR (if different)			
U.S. Army Corps of Engs				County of Alameda DPW			
211 Main Street				399 Elmhurst Street			
San Francisco	CA 94102			Hay	ward	<u>CA</u> 94544	
Fill out the section below and annotate the diagram on the reverse. Show north arrow or direction of current.							
TYPE OF LIGHTS	Number of Lights	Are Lights Correctly Placed?	of F	Lights Proper or/Arc?	Are Lights Visible for 1 Naut. Mi?	State Condition of Lights	
Channel Center Lights	0						
Margin of Channel Lights	0						
Pier Lights	2						
Pier Axis Lights	0						
Movable Span Lights	2						
Preferred Channel Lights	0						
OTHER FEATURES	How Many?	LLNR	Chara	acterist	ic Range	Working Properly?	
Fog Signals	0	0	١	N/A	N/A		
Raco ns	0	0	١	N/A	N/A		
Condition of fenders:	Condition of vertical clearance gauges:						
Is the bridge name shown? What name is shown?						Is sign visible to mariners?	
Are navigational clearances impaired by disrepair, cables, etc? Are nav. clearances impaired by accumulation of debris?							
Is there any equipment (e.g. barges, scaffolds) in the navigation spans that is not listed in the LNM/BNM?							
If a drawbridge, is it capable of operating? Are the operating regulations posted? Discrepant							
Is there evidence of bridge or fender damage that might be from vessels						Watching properly	
Date and Time of Survey	Name and N	Name and Member Number Signature of Surveyor				Home Telephone Number	
	Signature o					Aux. File Number 18	

Secondary Observer(s):	Aux. #:
	Aux. #:
	Aux. #: Aux. #:
Green Red Open	Red Red Red Closed
Red ∰ Red Red / Green ER	North arrow † # dolphin - FT. R.A. LIFT BRIDGE
	Fruitvale RR Bridge
Red Red/Green	Red/Green
Red Re	Miller Sweeney Hwy Bridge
	Red/Green Red dolphin
Red	

Comments: The bridges at Fruitvale Avenue share some navigation lights and the railroad bridge is twice as long as the highway bridge, so the navigation lights have been "moved" to mark the actual navigation opening. Inspect both bridges at the same time.